Oil Field Environmental Incident Summary

Responsible Party: Oxy USA, Inc **Well Operator:** OXY USA INC.

Well Name: STATE KARY 4-19-18H-144-96

Field Name: MURPHY CREEK Well File #: 25708

Date Incident:7/20/2013Time Incident:10:10Facility ID Number:County:DUNNTwp:144Rng:96Sec:30Qtr:

Location Description:

Submitted By: Jerry Eubank Received By:

Contact Person: Terry Ryland

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.25 MilesDistance Nearest Water Well:0.25 Miles

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spilled	Units	Recovered	Units
Oil	0	barrels	0	barrels
Brine	0	barrels	0	barrels
Other	4	barrels	4	barrels

Description of Other Released Contaminant:

Oil Based Mud

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Followup Units

Potential Environmental Impacts:

Action Taken or Planned:

A vac company sucked up all oil based mud. Contaminated scoria was removed for disposal.

Wastes Disposal Location: Contaminated scoria was disposed of at clean harbors. Recovered oil

based mud was disposed of at Tervita.

Agencies Involved:

Updates

Date: 7/22/2013 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location, apparently during drilling activities, according to the report.